

## Nockenwellen-Arretierblock für Fiat / Lancia 1,4 12V

- A** Einlass-Nockenwellen-Arretierblock,  
markiert mit **A-2-CIL**  
für Einlassnockenwelle 2. Zylinder  
zu verwenden wie OEM 1870797000




### ALLGEMEINE INFORMATION

Dieses Werkzeug dient dem Überprüfen und Einstellen der Nockenwellen-Steuerzeiten. Der Werkzeug wird benötigt beim Zahnriemenwechsel und ist geeignet für Fiat Bravo, Brava & Lancia Y10 1,4 12V mit Motorcode: 182A3.000 / 182A5.000.

### SICHERHEITSHINWEISE

- Vorsicht bei Arbeiten an heißen Motoren, es besteht Verbrennungsgefahr!
- Vorsicht bei Arbeiten an laufenden Motoren. Lose Kleidung, Werkzeuge und andere Gegenstände können von drehenden Teilen erfasst werden und zu schweren Verletzungen führen.
- Entfernen Sie vor der Reparatur den Zündschlüssel, so verhindern Sie ein versehentliches Starten des Motors.
- Diese Anleitung dient als Kurzinformation und ersetzt keinesfalls ein Werkstatthandbuch. Verwenden Sie immer eine fahrzeugspezifische Serviceliteratur. Aus dieser entnehmen Sie bitte technische Angaben wie Drehmomentwerte, Hinweise zur Demontage / Montage usw.
- Nach erfolgter Reparatur bzw. vor dem Starten den Motor min. 2 Umdrehungen von Hand drehen und die Steuerzeiten erneut überprüfen.



## Camshaft Locking Tool for Fiat / Lancia 1.4 12V

- A** Inlet Camshaft Locking Tool,  
marked with **A-2-CIL**  
for inlet camshaft cylinder 2  
to be used as OEM 1870797000



### GENERAL INFORMATION

This timing tool set designed for checking and setting the camshaft timing. The tool set is required when replacing the timing belt and it is suitable for Fiat Bravo, Brava & Lancia Y10 1.4 12V with engine code: 182A3.000 / 182A5.000.

### SAFETY ADVICE

- Be careful when working on hot engines – risk of burn!
- Be careful when working on running engines. Loose clothes, tools and other things can be caught up in revolving parts which may lead to serious injuries.
- Remove the ignition key before repair so that the engine will not start unintentionally.
- This manual is just brief information and will not replace a workshop manual. Always consult specific service literature for information about torques, assemblies, disassemblies, etc.
- After any successful maintenance and before starting the engine, you should rotate the engine for two turns manually to check the new control time.

